## ATC-109

## Building Safety Evaluation after the February 22, 2011 Christchurch, New Zealand Earthquake: Observations by the ATC Reconnaissance Team

By the

APPLIED TECHNOLOGY COUNCIL 201 Redwood Shores Parkway, Suite 240 Redwood City, California 94065 E-mail: atc@atcouncil.org Website: www.atcouncil.org

Funded by the APPLIED TECHNOLOGY COUNCIL and the ATC ENDOWMENT FUND

Prepared for ATC by

RONALD GALLAGHER BRET LIZUNDIA JIM C. BARNES

## Preface

In June 2011 the Applied Technology Council (ATC) dispatched a small reconnaissance team to Christchurch, New Zealand to observe the building safety evaluation process following the magnitude-6.2 February 22, 2011 earthquake, one of several large earthquakes that significantly impacted Christchurch and the surrounding area on the South Island of New Zealand, beginning in September 2010. The ATC team spent one week in New Zealand, followed by additional research, including internet searches and the review of pertinent literature.

The outcomes of the building safety evaluation reconnaissance study were of particular interest to ATC because New Zealand conducted postearthquake safety evaluations using methodologies similar to those in the ATC-20 report, Procedures for Postearthquake Safety Evaluation of Buildings (ATC, 1989a), which has evolved into the defacto national standard in the United States. Moreover, the New Zealand earthquake series and related impacts occurred at a time when ATC was beginning to plan an update of the ATC-20 report and companion ATC-20-1 Field Manual: Postearthquake Safety Evaluation of Buildings, Second Edition (ATC, 2005)-an activity that could benefit from the reconnaissance efforts.

This ATC-109 report summarizes the reconnaissance team's observations, findings, and recommendations regarding postearthquake building safety evaluations. The report preparation process benefited from review comments received from New Zealand engineers and several U.S. and Canadian structural engineers who participated in the building safety evaluations in Christchurch immediately following the February 2011 event. Their observations and insights were very helpful in developing a picture of the immediate postearthquake situation and its subsequent evolution. The ATC team also relied on information provided in the earthquake investigation reports commissioned by the Canterbury Earthquakes Royal Commission, which was formed in response to the earthquake series and their devastating impacts on Christchurch.

The ATC reconnaissance team consisted of Bret Lizundia (lead), Ronald Gallagher, and Jim C. Barnes. Mr. Lizundia, a practicing structural engineer and a principal at Rutherford + Chekene in San Francisco, was the ATC Board President at the time of the trip. Mr. Gallagher, a structural engineer with R. P. Gallagher Associates in Oakland, California, led the development of the original ATC-20 report, Procedures for Postearthquake Safety Evaluation of Buildings (ATC, 1989a) and the companion ATC-20-1 Field Manual: Postearthquake Safety Evaluation of Buildings (ATC, 1989b). Mr. Barnes is a civil engineer with the California Governor's Office of Emergency Services (Cal OES) in Sacramento, California, where he is responsible for coordinating and overseeing the earthquake safety assessment program in California. All are experienced in the postearthquake safety evaluation procedures used in the United States and have observed safety evaluations following a number of damaging earthquakes.

ATC gratefully acknowledges the valuable assistance and generous help of the following organizations who assisted the ATC reconnaissance team and provided much useful information:

- Building Research Association of New Zealand (BRANZ);
- Canterbury Earthquake Recovery Authority (CERA);
- Christchurch City Council, Environmental Policy and Approval Unit (CCC EP&A);
- New Zealand Department of Building and Housing (DBH);
- Institution of Professional Engineers of New Zealand (IPENZ);
- New Zealand Ministry of Civil Defense & Emergency Management (MCDEM);
- New Zealand Society for Earthquake Engineering (NZSEE);
- Structural Engineers Association of California (SEAOC); and

• Structural Engineers Association of Washington (SEAW).

In addition, the valuable assistance and review comments of the following individuals are also gratefully acknowledged: Graeme Beattie (BRANZ), Russ Berkowitz (Forell/Elsesser Engineers), Mark Billinghurst (University of Canterbury). David Brunsdon (Kestrel Group and NZSEE), Paul Campbell (Opus), Tony Court (A.B. Court & Associates/SEAOC), Carl Devereux (Aurecon), Dmytro Dizhur (University of Auckland), Ken Elwood (University of Auckland), Helen Ferner (Beca), David Hopkins (DBH Consultant), John Hare (Holmes Group), Jason Ingham (University of Auckland), Janiele Maffei (California Earthquake Authority), Laurence Kornfield (City and County of San Francisco), Anne Mackenzie (Build Green), Steve McCarthy (CCC EP&A), Lisa Moon (University

of Adelaide), Kelvin Newman (CCC EP&A), Patrick Scofield (CCC EP&A), Richard Sharpe (Beca), Marko Schotanus (Rutherford + Chekene/SEAOC), John Snook (CERA), Mike Stannard (DBH), Dave Swanson (Reid Middleton/SEAW), Fred Turner (California Seismic Safety Commission), and Peter Wood (MCDEM and NZSEE).

Funding to cover the travel expenses of the ATC reconnaissance team and for the development of this report was provided by the Applied Technology Council and the ATC Endowment Fund. Report preparation services were provided by Amber Houchen and Peter N. Mork of the Applied Technology Council and Xanthia Tucker, who served as copy editor.

Christopher Rojahn ATC Executive Director

Note on Images: Photographs in the report were taken by the reconnaissance team unless otherwise noted. Sources for other illustrations are indicated where shown.

## Contents

Pref	ace		iii	
List of Figures				
List	of Tables		ix	
1.	Introc 1.1	luction Background and Purpose		
	1.2	Brief Overview of the Canterbury Earthquakes		
	1.3	Devastating Effects on Christchurch	3	
	1.4	Brief Overview of Building Safety Evaluation in Christchurch		
	1.5	Background on the Development of the ATC-20 Procedures		
	1.6	Organization and Scope of this Report		
2.		enges Encountered after the Earthquake		
	2.1	Scale and Extent of Liquefaction	7	
	2.2	Combination of Strong Shaking and Liquefaction		
	2.3	Large Scale Ground Settlement		
	2.4	Number of High-Rise Buildings Seriously Damaged		
	2.5	Concentration of Damage in Central Business District		
	2.6 2.7	Large, Damaging Aftershocks		
	2.7	Safety Evaluations Conducted with Limited Preparedness		
	2.8	Fractured Rebar in Shear Walls	14	
3.	Useful Ideas and Practices Observed			
	3.1	Use of Triage		
	3.2	Use of Indicator Buildings		
	3.3	Emergency Stabilization of Mid-Rise and High-Rise Buildings		
	3.4	Central Business District Cordon.		
	3.5	Use of Laser Scanner for Slope Stability Monitoring	22	
	3.6	Shelter-in-Place Strategies	24	
	3.7	High Priority Evaluation of Shopping Centers and Drug Stores	24	
	3.8	Use of Shipping Containers as Barricades	25	
	3.9	Targeted Safety and Evaluation Teams		
	3.10	Use of Private Engineers for Safety Evaluations		
	3.11	Damage Reconnaissance by Remote Means		
	3.12	Land Management Issues and Recovery	27	
	3.13	Use of USAR Personnel as Safety Escorts		
	3.14	Use of On-Call Locksmiths for Building Access		
	3.15	Use of Internet and Social Media for Information Updates		
	3.16	Introduction of Usability Categories	29	
4.	Safety Evaluation Issues in Christchurch			
	4.1	New Zealand Safety Evaluation Guidance		
	4.2	Safety Evaluations Performed by Personnel with Limited Training		
	4.3	Safety Evaluations Slowed by Lack of a Pool of Prequalified Personnel		
	4.4	Fading Ink on Placards		

	4.5 4.6	Old Placards Often Not Removed Full Advantage of the RESTRICTED USE Placard Not Taken		
5.	Preparation and Management of Safety Evaluations			
5.	5.1	Lack of a Prior Program to Train Safety Evaluators and Coordinators		
	5.2	No Prior Large Cache of Placards, Assessment Forms, and Supplies		
	5.2	Welfare Personnel Added to Safety Evaluation Teams		
	5.3 5.4			
		Placard Meanings Not Well Understood by the Public		
	5.5	Number and Location of URM Buildings Unknown		
	5.6	Placards Used as Basis for Rendering Aid		
	5.7	Laws Hampering the Placarding Process		
	5.8	Lack of Guidelines for Engineering Evaluations of Damaged Buildings		
	5.9	Lack of Repair Guidelines for Damaged Buildings	38	
6.	Resea	arch and Development Needs		
	6.1	Research Needs		
		6.1.1 Understanding Fractured Bars in Shear Walls		
		6.1.2 Seismic Strengthening of URM Cavity Walls		
		6.1.3 Investigation of the Performance of Adhesive Anchors	39	
		6.1.4 Strong Motion Instrumentation of Buildings in New Zealand	40	
		6.1.5 Performance of Building Shoring and Stabilization Methods		
		6.1.6 Building Damage Assessment by Instrumentation and Measurement		
	6.2	Guideline Document and Training Needs		
		6.2.1 Guidelines for Engineering Evaluation and Repair of Damaged Buildings		
		6.2.2 Guidance for Repairing or Removing Buildings Damaged by Liquefaction		
		6.2.3 Development of Seismic Design Criteria for Stairs		
		6.2.4 Guidelines for Management of Postearthquake Safety Evaluations		
		6.2.5 Guidelines for Cordoning, Barricading, Shoring, and Emergency Stabilization		
		6.2.6 Guidelines for Private Engineer Posting of Buildings		
		6.2.8 Usability Categories		
		6.2.9 Aftershock Risk		
		6.2.10 Shelter-in-Place Guidelines		
		6.2.11 Digital Records		
		6.2.12 Postearthquake Safety Placard Status During the Recovery Period		
	6.3	International Collaboration Opportunities		
	6.4	Recommendations for Future Development of U.S. Guideline Documents		
		6.4.1 Initial Steps	46	
		6.4.2 High Priority Guideline Documents and Training Programs	46	
		6.4.3 Other Important Guideline Documents	46	
	6.5	Summary Thoughts for the Future	46	
Apper	ndix A:	Placards, Checklists, and Forms Used in Christchurch	49	
Apper	ndix B:	New Zealand Memorandum of Understanding (MOU) for Engineers Volunteering to Con	nduct	
11		Private-Sector Building Safety Evaluations		
Refer	ences		63	
Projec	et Partici	ipants	67	
Appli	ed Tech	nology Council Projects and Report Information	69	
Appli	ed Tech	nology Council Directors	85	