

FEMA 306

EVALUATION OF EARTHQUAKE DAMAGED CONCRETE AND MASONRY WALL BUILDINGS

Basic Procedures Manual

Prepared by:



Applied Technology Council (ATC-43 Project)

555 Twin Dolphin Drive, Suite 550
Redwood City, California 94065

Prepared for:

The Partnership for Response and Recovery

Washington, D.C.

Funded by:

Federal Emergency Management Agency

1998

Applied Technology Council

The Applied Technology Council (ATC) is a nonprofit, tax-exempt corporation established in 1971 through the efforts of the Structural Engineers Association of California. ATC is guided by a Board of Directors consisting of representatives appointed by the American Society of Civil Engineers, the Structural Engineers Association of California, the Western States Council of Structural Engineers Associations, and four at-large representatives concerned with the practice of structural engineering. Each director serves a three-year term.

The purpose of ATC is to assist the design practitioner in structural engineering (and related design specialty fields such as soils, wind, and earthquake) in the task of keeping abreast of and effectively using technological developments. ATC also identifies and encourages needed research and develops consensus opinions on structural engineering issues in a nonproprietary format. ATC thereby fulfills a unique role in funded information transfer.

Project management and administration are carried out by a full-time Executive Director and support staff. Project work is conducted by a wide range of highly qualified consulting professionals, thus incorporating the experience of many individuals from academia, research, and professional practice who would not be available from any single organization. Funding for ATC projects is obtained from government agencies and from the private sector in the form of tax-deductible contributions.

1998-1999 Board of Directors

Charles H. Thornton, President
Edwin T. Dean, Vice President
Andrew T. Merovich, Secretary/
Treasurer
C. Mark Saunders, Past President
James R. Cagley
Arthur N. L. Chiu
Robert G. Dean

Edwin H. Johnson
Kenneth A. Luttrell
Newland J. Malmquist
Stephen H. Pelham
Richard J. Phillips
Charles W. Roeder
Jonathan G. Shipp

Notice

This report was prepared under Contract EMW-95-C-4685 between the Federal Emergency Management Agency and the Partnership for Response and Recovery.

Any opinions, findings, conclusions, or recommendations expressed in this publication do not necessarily reflect the views of the Applied Technology Council (ATC), the Partnership for Response and Recovery (PaRR), or the Federal Emergency Management Agency (FEMA). Additionally, neither ATC, PaRR, FEMA, nor any of their employees makes any warranty, expressed or implied, nor assumes any legal liability or responsibility for the accuracy, completeness, or usefulness of any information, product, or process included in this publication. Users of information from this publication assume all liability arising from such use.

For further information concerning this document or the activities of the ATC, contact the Executive Director, Applied Technology Council, 555 Twin Dolphin Drive, Suite 550, Redwood City, California 94065; phone 650-595-1542; fax 650-593-2320; e-mail atc@atcouncil.org.

Preface

Following the two damaging California earthquakes in 1989 (Loma Prieta) and 1994 (Northridge), many concrete wall and masonry wall buildings were repaired using federal disaster assistance funding. The repairs were based on inconsistent criteria, giving rise to controversy regarding criteria for the repair of cracked concrete and masonry wall buildings. To help resolve this controversy, the Federal Emergency Management Agency (FEMA) initiated a project on evaluation and repair of earthquake damaged concrete and masonry wall buildings in 1996. The project was conducted through the Partnership for Response and Recovery (PaRR), a joint venture of Dewberry & Davis of Fairfax, Virginia, and Woodward-Clyde Federal Services of Gaithersburg, Maryland. The Applied Technology Council (ATC), under subcontract to PaRR, was responsible for developing technical criteria and procedures (the ATC-43 project).

The ATC-43 project addresses the investigation and evaluation of earthquake damage and discusses policy issues related to the repair and upgrade of earthquake-damaged buildings. The project deals with buildings whose primary lateral-force-resisting systems consist of concrete or masonry bearing walls with flexible or rigid diaphragms, or whose vertical-load-bearing systems consist of concrete or steel frames with concrete or masonry infill panels. The intended audience is design engineers, building owners, building regulatory officials, and government agencies.

The project results are reported in three documents. The FEMA 306 report, *Evaluation of Earthquake Damaged Concrete and Masonry Wall Buildings, Basic Procedures Manual*, provides guidance on evaluating damage and analyzing future performance. Included in the document are component damage classification guides, and test and inspection guides. FEMA 307, *Evaluation of Earthquake Damaged Concrete and Masonry Wall Buildings, Technical Resources*, contains supplemental information including results from a theoretical analysis of the effects of prior damage on single-degree-of-freedom mathematical models, additional background information on the component guides, and an example of the application of the basic procedures. FEMA 308, *The Repair of Earthquake Damaged Concrete and Masonry Wall Buildings*, discusses the policy issues pertaining to the repair of earthquake damaged buildings and illustrates how the procedures developed for the project can be used to provide a technically sound basis for policy decisions. It

also provides guidance for the repair of damaged components.

The project also involved a workshop to provide an opportunity for the user community to review and comment on the proposed evaluation and repair criteria. The workshop, open to the profession at large, was held in Los Angeles on June 13, 1997 and was attended by 75 participants.

The project was conducted under the direction of ATC Senior Consultant Craig Comartin, who served as Co-Principal Investigator and Project Director. Technical and management direction were provided by a Technical Management Committee consisting of Christopher Rojahn (Chair), Craig Comartin (Co-Chair), Daniel Abrams, Mark Doroudian, James Hill, Jack Moehle, Andrew Merovich (ATC Board Representative), and Tim McCormick. The Technical Management Committee created two Issue Working Groups to pursue directed research to document the state of the knowledge in selected key areas: (1) an Analysis Working Group, consisting of Mark Aschheim (Group Leader) and Mete Sozen (Senior Consultant) and (2) a Materials Working Group, consisting of Joe Maffei (Group Leader and Reinforced Concrete Consultant), Greg Kingsley (Reinforced Masonry Consultant), Bret Lizundia (Unreinforced Masonry Consultant), John Mander (Infilled Frame Consultant), Brian Kehoe and other consultants from Wiss, Janney, Elstner and Associates (Tests, Investigations, and Repairs Consultant). A Project Review Panel provided technical overview and guidance. The Panel members were Gregg Borchelt, Gene Corley, Edwin Huston, Richard Klingner, Vilas Mujumdar, Hassan Sassi, Carl Schulze, Daniel Shapiro, James Wight, and Eugene Zeller. Nancy Sauer and Peter Mork provided technical editing and report production services, respectively. Affiliations are provided in the list of project participants.

The Applied Technology Council and the Partnership for Response and Recovery gratefully acknowledge the cooperation and insight provided by the FEMA Technical Monitor, Robert D. Hanson.

Tim McCormick
PaRR Task Manager

Christopher Rojahn
ATC-43 Principal Investigator
ATC Executive Director

Table of Contents

Preface	iii
List of Figures	ix
List of Tables	xi
List of Test and Inspection Guides	xiii
List of Component Damage Classification Guides	xv
Prologue	xvii
What have we learned?	xvii
What does it mean?	xviii
1. Introduction and Overview	1
1.1 Purpose	1
1.2 Scope	1
1.3 Basis	2
1.4 Overview of the Damage Investigation and Evaluation Procedures	4
1.4.1 Introduction and Overview	4
1.4.2 Characteristics of Concrete and Masonry Wall Buildings	4
1.4.3 Investigation of Earthquake Damage	4
1.4.4 Evaluation of Earthquake Damage	6
1.4.5 Component Information	7
1.4.6 Terms and Symbols	7
1.4.7 Related Documents	7
1.5 Limitations	8
2. Characteristics of Concrete And Masonry Wall Buildings	9
2.1 Typical Vertical Elements	9
2.1.1 Bearing Walls and Infilled Frames	9
2.1.2 Wall Elevations	10
2.1.3 Foundation Effects	10
2.2 Horizontal Elements	10
2.3 Three-Dimensional Considerations	14
2.4 Identification of Components	14
3. Investigation of Earthquake Damage	17
3.1 Characteristics of the Damaging Earthquake	17
3.2 Review of Existing Building Data	17
3.3 Assessing the Consequences of the Damaging Earthquake	18
3.4 Pre-existing Conditions	22
3.5 Component Damage Classification	23

3.6	Verification	24
3.7	Documentation	26
3.8	Test and Inspection Guides	29
4.	Evaluation of Earthquake Damage	61
4.1	Basis of Evaluation	61
4.2	Seismic Performance Objectives	61
4.3	Seismic Performance Parameters	61
4.4	Relative Performance Analysis	62
4.4.1	Overview	62
4.4.2	Global Displacement Performance Limits	64
4.4.3	Component Modeling and Acceptability Criteria	65
4.4.4	Global Displacement Demand	70
4.5	Performance Restoration Measures	74
4.6	An Alternative—The Direct Method	75
5:	Reinforced Concrete	77
5.1	Introduction and Background	77
5.2	Reinforced Concrete Component Types and Behavior Modes	77
5.2.1	Component Types	77
5.2.2	Behavior Modes and Damage	77
5.2.3	Behavior Modes with High Ductility Capacity (Flexural Response)	78
5.2.4	Behavior Modes with Intermediate Ductility Capacity	78
5.2.5	Behavior Modes with Little or No Ductility Capacity	82
5.2.6	Foundation Rocking Response	83
5.3	Reinforced Concrete Evaluation Procedures	83
5.3.1	Cracking	83
5.3.2	Expected Strength and Material Properties	84
5.3.3	Plastic-Hinge Location and Length	85
5.3.4	Ductility Classifications	86
5.3.5	Moment Strength	87
5.3.6	Shear Strength	88
5.3.7	Wall Boundary Confinement	90
5.3.8	Lap Splice Strength	91
5.3.9	Wall Buckling	92
5.4	Symbols for Reinforced Concrete	93
5.5	Reinforced Concrete Component Guides	95
6:	Reinforced Masonry	107
6.1	Introduction and Background	107
6.2	Reinforced Masonry Component Types and Behavior Modes	108
6.2.1	Component Types	108
6.2.2	Behavior Modes with High Ductility	109
6.2.3	Behavior Modes with Moderate Ductility	113
6.2.4	Behavior Modes with Low Ductility	113

6.3	Reinforced Masonry Evaluation Procedures	114
6.3.1	Material Properties	114
6.3.2	Flexure	114
6.3.3	Shear	116
6.3.4	Sliding	117
6.3.5	Wall Instability	117
6.3.6	Lap-Splice Slip	118
6.3.7	Masonry Beams	118
6.4	Symbols for Reinforced Masonry	120
6.5	Reinforced Masonry Component Guides	121
7:	Unreinforced Masonry	137
7.1	Introduction and Background	137
7.1.1	Section Organization	137
7.1.2	Material Types and Structural Framing	137
7.1.3	Seismically Rehabilitated URM Buildings	138
7.2	Unreinforced Masonry Component Types and Behavior Modes	139
7.2.1	Non-Wall Components	139
7.2.2	Wall Components	142
7.2.3	Foundation Rocking	144
7.2.4	Wall-Pier Rocking	144
7.2.5	Bed-Joint Sliding	146
7.2.6	Bed-Joint Sliding at Wall Base	149
7.2.7	Spandrel-Joint Sliding	150
7.2.8	Rocking/Toe Crushing	150
7.2.9	Flexural Cracking/Toe Crushing/Bed Joint Sliding	151
7.2.10	Flexural Cracking/Diagonal Tension	151
7.2.11	Flexural Cracking/Toe Crushing	151
7.2.12	Spandrel-Unit Cracking	152
7.2.13	Corner Damage	152
7.2.14	Preemptive Diagonal Tension	152
7.2.15	Preemptive Toe Crushing	152
7.2.16	Out-of-Plane Flexural Response	153
7.2.17	Other Modes	154
7.3	Unreinforced Masonry Evaluation procedures	154
7.3.1	Overview	154
7.3.2	Evaluation Procedures for In-Plane Behavior of Piers in Walls with Weak Pier - Strong Spandrel Mechanisms	155
7.3.3	Evaluation Procedures for In-Plane Behavior of Solid Wall Components	157
7.3.4	Evaluation Procedures for In-Plane Behavior of Perforated Walls with Spandrel Damage	157
7.3.5	Evaluation Procedures for Out-of-Plane Behavior of Wall and Pier Components	162
7.4	Symbols for Unreinforced Masonry	163
7.5	Unreinforced Masonry Component Guides	165

8:	Infilled Frames	183
8.1	Introduction and Background	183
8.2	Infilled Frame Masonry Component Types and Behavior Modes	184
8.2.1	Component Types	184
8.2.2	Panel and Frame Modeling and Interaction	187
8.2.3	Behavior Modes	187
8.3	Infilled Frame Evaluation Procedures	197
8.3.1	Solid Infilled-Panel Components	197
8.3.2	Infilled-Panel Components with Openings	199
8.3.3	Out-of-Plane Behavior of Infilled-Panel Components	199
8.3.4	Steel-Frame Components	200
8.3.5	Concrete-Frame Components	200
8.4	Infilled Frame Component Guides	205
	Glossary	215
	List of General Symbols	217
	References	219
	ATC-43 Project Participants	233
	Applied Technology Council Projects And Report Information	237