

## TABLE OF CONTENTS

PREFACE.....	iii
EXECUTIVE SUMMARY .....	vii
1. SANTA CLARITA CITY HALL; NORTHRIDGE EARTHQUAKE DAMAGE Meklyn Green.....	1-1
2. EVALUATION OF THE DAMAGE TO THE BORAX CORPORATE HEADQUARTERS BUILDING AS A RESULT OF THE NORTHRIDGE EARTHQUAKE Jerome F. Hajar, David P. O'Sullivan, Roberto T. Leon, Brett C. Gourley .....	2-1
3. POST EARTHQUAKE STUDIES OF A DAMAGED LOW RISE OFFICE BUILDING James C. Anderson, Roy G. Johnson, James E. Partridge .....	3-1
APPENDIX A: SAC PROGRAM TO REDUCE THE EARTHQUAKE HAZARDS OF STEEL MOMENT FRAME STRUCTURES, AN OVERVIEW .....	A-1